

FIG. 1




FIG. 2




FIG.3




FIG.4




FIG. 5




FIG.6A




FIG.6B




FIG.7A




FIG.7B




FIG.9




FIG.10




FIG.11




FIG.12




FIG.13




FIG. 14





FIG.15






FIG.17




FIG.18




FIG.19




FIG.20




FIG.21A




FIG.21B




FIG.22A




FIG.22B




FIG.23A




FIG.23B




FIG.24




FIG.25





FIG.26



- A: MAGNETIC BODY IS FIXED BY PRESS FIT
B: PART OF MAGNETIC BODY IS FIXED BY WELDING
C: MAGNETIC BODY IS FULLY FIXED BY WELDING

FIG.27




FIG. 28A




FIG. 28B




FIG. 28C




FIG. 28D




FIG. 28E




FIG. 28F




FIG.29




FIG.30




FIG.31




FIG.32A




FIG.32B




FIG.33A




FIG.33B




FIG.34A




FIG.34B




FIG.34C




FIG.35




FIG.36A




FIG.36B




FIG.37




FIG.38A PRIOR ART




FIG.38B




FIG.39A PRIOR ART




FIG.39B




FIG.39C




FIG. 40




FIG.41 PRIOR ART




FIG.42 PRIOR ART




FIG.43 PRIOR ART




FIG.44 PRIOR ART




FIG.45A PRIOR ART




FIG.45B PRIOR ART

